

SERVICE PARTS LIST 54-U
SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS REVISED BULLETIN
54-04-0376 DATE 54-04-0376 June 2004 **CHARGER - ALBION** WIRING INSTRUCTION SERIAL NUMBER

411D

CATALOG EXAMPLE: 860-48-59-6561 **NUMBER**

Component Parts (Small #) Are Included When Ordering The Assembly (Large #).

6


Insert strain relief

inside wall of the charger housing.

as shown with the flat

side of the strain relief

positioned against the



Rib of top housing is to separate the terminals of circuit board assembly and the cord set wires.



4

★5 6

7

8

12-20-1285

22-64-0920

NOTES Fully seat circuit board assembly into top housing, 5,8 aligning the bosses.

Bottom Housing

Top Housing

Cordset

Service Nameplate Kit

Circuit Board Assembly

- 5,8 Circuit board battery clips are to be fully inserted into battery port of top housing.
- 5,6 Cord set terminals are to be fully seated on mating terminals of printed circuit board assembly and perpendicular to printed circuit board surface.
- 6.8 Cord set to be free from conductor twists and cord crossover prior to installation of strain relief into top housing.

ALBION ENGINEERING COMPANY

2080A WHEATSHEAF LANE PHILADELPHIA, PA 19124-5091

PHONE: 215-535-3476 FAX: 215-744-4719 www.albioneng.com

NO. REQ.

(4)

(1)

(1)

(1)

(1)

(1)

(1)