



BOSCH

Cordl Reciprocating Saw

GSA 18 V-LI | 3 601 F4J 080

Table of Content

Spare parts list.....	2
Illustration - Type.....	4

Spare parts list

Item	Part Number	Description
2	2 610 942 109	Pole housing 14;4-24V
3	2 610 957 808	Armature 18V
4	1 607 233 567	Electronics Module
13	1 619 P01 511	Ball Bearing
14	1 900 905 173	groove ball bearing 6000-2RS DIN 625
19	2 610 315 386	Screw ST3,9x19
22	1 619 P01 127	Rubber Ring
24	2 604 690 055	Compression Spring
27	2 610 956 663	Set Of Handles BLUE
28	2 610 908 804	Protective Washer
29	2 610 934 995	mat seal
31	2 610 935 103	Front Housing
35	2 610 934 999	Sintered-Metal Bushing
36	2 610 944 393	Spindle Assembly
37	2 610 935 431	Spring Retaining Plate
39	2 610 030 004	Felt Washer SP 14,0
40	2 610 995 815	Shaft Seal
41	2 610 935 004	Plastic Collar
42	2 610 908 698	Bearing Shell
43	2 610 942 118	Conversion Gear
45	2 610 935 005	Supporting foot
47	2 610 937 437	Compression Spring
48	2 610 935 008	Insulating Sleeve
50	2 610 938 887	Wobble Plate
53	2 610 935 010	Retaining Plate
61	1 900 905 162	groove ball bearing 15x32x9
62	2 610 918 051	Trunnion
82	2 610 935 014	Baffle
85	2 610 956 664	Selector Switch
86	2 610 956 683	Sliding Plate
88	1 619 P01 446	Screw
89	1 619 P06 252	Torx Oval-Head Screw
90	1 603 435 068	Thread-forming tap. Screw DIN 7500, M4x10, SR10.2
91	1 619 P01 932	Screw BLACK

Spare parts list

Item	Part Number	Description
92	1 619 P01 447	Screw
93	1 619 P01 931	Screw BLACK
651	1 607 A35 0M0	Battery Pack GBA 18V 4.0Ah
653	2 607 225 937	Charger CN GAL 1880 CV 220V/14,4-18V
653	2 607 226 267	Fast Charger CN GAL 18V-40
804	1 609 280 478	Contact retainer
808	1 619 P16 859	Nameplate
810	2 610 943 623	Carbon-Brush Set
830	2 610 945 335	Bearing Plate
857	2 610 920 684	Toolholder
883	3 602 391 503	Rubber Buffer

Illustration - Type - E

3 601 F4J 000
 Issue | 09-03-16
 Stand | **Fig./Abb. 1**

