



**BOSCH**

# Cordless Drill Driver

GSR 10,8-2-LI | 3 601 H68 180

---

## Table of Content

Spare parts list.....	2
Illustration - Type.....	3

**Cordless Drill Driver | GSR 10,8-2-LI | 3 601 H68 180****Spare parts list**

<b>Item</b>	<b>Part Number</b>	<b>Description</b>	
1	2 609 100 824	Housing	BLUE
4	1 607 233 5DK	Electronics Module	
5	2 609 100 825	Changeover Lever	
9	2 609 132 377	Manufacturer's nameplate	GSR 10,8-2-LI
20	2 609 100 826	Lens	
25	2 609 110 967	Keyless Chuck	
32	2 609 199 279	Switchover Unit	
41	2 609 132 378	Sticker	
45	2 609 199 786	Gear Box	
70	2 609 110 537	Clip	
91	1 607 A35 0C5	Battery Pack	GBA 12V 2.0Ah Li SCM
101	2 609 110 883	Screw	
107	2 603 421 229	Countersunk-Head Screw LEFTHAND THREADS	M6x23
653	2 607 225 137	Fast Charger	AUS 240/10,8V
653	2 607 225 303	Fast Charger	CN 220/10,8V, 30 MIN.
802	2 609 199 258	DC motor	10,8V - 12V
808	2 609 132 503	Nameplate	

Illustration - Type - E

3 601 H68 100  
 Stand | 09-07  
 Issue | 09-06-12 **Fig./Abb. 1**

