



**BOSCH**

# Cordless Drill Driver

GSR 18V-90 C | 3 601 JK6 080

---

## Table of Content

Spare parts list.....	2
Illustration - Type.....	3

**Spare parts list**

<b>Item</b>	<b>Part Number</b>	<b>Description</b>	
1	1 600 A01 V6W	Housing	
2	1 600 A01 W0T	Stator	
4	1 607 233 5JS	Electronics Module	
4/30	1 607 504 124	Printed-Board Assembly	
5	1 600 A02 3EE	Changeover Lever	
6	2 607 202 904	Switch	
7	1 600 A02 5PZ	Cover unit	
9	1 601 11C 4MF	Manufacturer's nameplate	
16	1 600 A01 6CZ	Electronics Module	
17	1 600 A02 KY7	Cover Panel	
25	1 600 A01 22S	Keyless Chuck	
32	1 600 A02 477	Switchover Unit	
45	1 600 A02 5H6	Gear Box	
50	1 600 A02 5W9	Separator	
91	1 607 A35 0MA	Battery Pack	GBA 18V 2.0Ah
100/10	2 609 111 584	Clip	
100/20	2 609 110 834	Screw	
101	2 609 110 353	Torx Oval-Head Screw	
107	2 603 421 229	Countersunk-Head Screw LEFTHAND THREADS	M6x23
653	2 607 226 267	Fast Charger	CN GAL 18V-40
658	2 609 199 748	Bit holder	
803	1 600 A02 9PG	Rotor	
808	1 601 11A 9DN	Nameplate	

Illustration - Type - E

