



BOSCH

Cordless Drill Driver

TSR 1080-2-LI | 3 601 JE2 080

Table of Content

Spare parts list.....	2
Illustration - Type.....	3

Spare parts list

Item	Part Number	Description
1	2 609 101 637	Housing
4	2 609 125 169	Electronics Module
5	2 609 101 391	Adjusting lever
25	2 609 110 495	Keyless Chuck Ø1,0-10 MM, 3/8
32	2 609 199 754	Switchover Unit
45	2 609 199 660	Gear Box
70	2 609 110 838	Clip
91	1 607 A35 0C5	Battery Pack GBA 12V 2.0Ah Li SCM
101	2 609 111 496	Screw
107	2 609 111 314	Countersunk-Head Screw
653	2 607 225 529	Fast Charger CN 220/3,6-10,8V, 1h
653	2 609 120 544	Fast Charger CN GAL 1110 CV 220/10,8V
802	2 609 199 724	Motor Spare Parts Set 10,8V

Illustration - Type - E

3 601 JE2 080
 Stand } 14-01-20
 Issue }

Fig./Abb. 1

