

Combi Orbital Sander P - F 012 727 50A - 7275

Item	Part Number	Description	Illustration	Price	Quantity	Price Group
1	2 610 993 892	Motor Housing	1	-,-	1	22
2	2 610 352 766	Field 120V	1	-,-	1	29
3	2 610 352 765	Armature 120V	1	-,-	1	-
4	2 610 910 115	Switch	1	-,-	1	21
5	1 619 X00 506	Power supply cord	1	-,-	1	-
5/1	2 610 352 788	Terminal	1	-,-	1	11
5/2	2 610 318 744	Terminal	1	-,-	1	12
8	2 610 995 445	Reference Plate	1	-,-	1	15
13	2 610 351 861	Ball Bearing	1	-,-	1	23
14	1 619 P01 511	Ball Bearing	1	-,-	1	19
15	2 610 352 751	Fan	1	-,-	1	17
16	2 610 320 548	Brush Holder	1	-,-	2	13
18	1 619 P01 508	Screw	1	-,-	2	10
20	2 610 931 268	Retaining snap ring	1	-,-	1	-
22	2 610 905 768	Nameplate	1	-,-	1	15
29	2 615 296 825	On-Off Switch	1	-,-	1	11
30	2 610 038 610	Cable 50 MM BLACK	1	-,-	1	13
31	2 610 038 852	Connecting Cable 50 MM BLUE	1	-,-	2	11
35	2 610 350 103	Pin	1	-,-	2	11
38	2 610 905 503	Guide Piece	1	-,-	2	16
39	2 610 902 933	Swing-Plate	1	-,-	1	18
41	2 610 902 932	Lever	1	-,-	2	15
43	2 610 042 699	Deep-Groove Ball Bearing	1	-,-	1	22
49	1 619 X00 504	Screw	1	-,-	7	10
54	2 610 352 839	Lever	1	-,-	2	13
810	2 610 321 617	Carbon-Brush Set	1	-,-	1	24
840	2 610 352 840	Base Support	1	-,-	1	21

