



Operating Instructions and Parts Manual

35" x 20" Woodturning Lathe


Model 3520C



Powermatic
427 New Sanford Road
LaVergne, Tennessee 37086
Ph.: 800-274-6848
www.powermatic.com

Part No. M-1353001
Edition 1 08/2017
Copyright © 2017 Powermatic

15.1.1 3520C Headstock Assembly – Exploded View




15.1.2 3520C Headstock Assembly – Parts List

| Index No. | Part No. | Description | Size | Qty |
|------------------|-----------------|------------------------------------|------------------|------------|
| 1 | 6294725 | Spur Center | MT2 | 1 |
| 2 | 6294736 | Faceplate (includes #17 and 102) | 1-1/4-8, Ø 3" | 1 |
| 3 | 6295796 | Nylon Insert Socket Set Screw | 1/4"-20 x 3/8" | 4 |
| 4 | 3520C-104 | Spindle | | 1 |
| 5 | F014007 | Flat Key, Dbl Rd Hd | 8x8x40mm | 1 |
| 6 | F014008 | Flat Key, Dbl Rd Hd | 8x8x80mm | 1 |
| 7 | BB-6207ZZ | Bearing | 6207ZZ | 2 |
| 8 | 3520B-208 | Bushing | | 1 |
| 9 | JWL1642-174 | Locking Collar | | 1 |
| 10 | TS-0270021 | Socket Set Screw | 5/16"-18 x 5/16" | 3 |
| 11 | 3520C-111 | Spindle Pulley | | 1 |
| 12 | 6077228 | Belt | 260J-10V | 1 |
| 13 | F006048 | C-Retaining Ring, Ext | S-22 | 1 |
| 14 | SR-6P3 | Strain Relief | SR-6P3 | 2 |
| 15 | TS-2246252 | Socket Head Button Screw | M6-1.0x25 | 2 |
| 16 | JWL1640EVS-125 | Sensor with Cable | | 1 |
| 17 | 6295796 | Nylon Insert Socket Set Screw | 1/4"-20x3/8" | 2 |
| 18 | 3520B-273 | Socket Set Screw | #10-24x1" | 1 |
| 19 | JWL1642-127 | Machine Screw | M3-0.5x10 | 4 |
| 20 | F009669 | Socket Head Button Screw | #10-24x3/8" | 2 |
| 21 | 3520C-121 | Bracket | | 1 |
| 22 | TS-0560071 | Hex Nut | #10-24 | 2 |
| 23 | 3520C-123 | Spindle Encoder PCB Assembly | | 1 |
| 24 | 3058001 | Clamp Bolt | | 1 |
| 25 | 3092095 | Clamp | | 1 |
| 26 | 6520009 | Hex Nylon Lock Nut | 5/8"-11 | 1 |
| 27 | 3520C-127 | Lock Handle Assembly | | 1 |
| 28 | TS-0271031 | Socket Set Screw | 3/8"-16 x 3/8" | 2 |
| 29 | 6095038 | Bushing | | 1 |
| 30 | 3520C-130 | Spindle Lock Plunger Seat | | 1 |
| 31 | 3520C-131 | Headstock Eccentric Shaft | | 1 |
| 32 | 3520B-275 | Spindle Comparator Spur Center | | 1 |
| 33 | 6644005 | Plunger Retainer | | 1 |
| 34 | TS-0209061 | Socket Head Cap Screw | 3/8"-16x1-1/4" | 2 |
| 35 | TS-0720091 | Lock Washer | 3/8" | 3 |
| 36 | 3064711 | Lathe Guard Bracket | | 1 |
| 37 | 3520C-137 | Headstock Casting | | 1 |
| 38 | 3520C-138 | Spring | | 1 |
| 39 | 3520C-139 | Spindle Lock Pin | | 1 |
| 40 | 3520C-140 | Cover Plate (includes #94) | | 1 |
| 41 | 3520C-141 | Control Box Assembly | | 1 |
| 42 | F010675 | Flat Head Socket Screw | #10-24x3/8" | 2 |
| 43 | LM000303 | Speed Label, 3520C | | 1 |
| 44 | 6295717 | Knob | M8 | 1 |
| 45 | 3520C-145 | Access Door (includes #43 and 101) | | 1 |
| 46 | TS-1490021 | Hex Cap Screw | M8-1.25x16 | 1 |
| 47 | F010878 | Flat Head Socket Screw | M3-0.5x10 | 2 |
| 48 | 3520C-148 | Magnet | | 2 |
| 49 | BB-6206VV | Bearing | 6206VV | 1 |
| 50 | 6864006 | Bearing Lock Washer | | 1 |
| 51 | 6549006 | Bearing Nut | | 1 |
| 52 | 3271081 | Handwheel | | 1 |
| 53 | 3719189 | Motor Sheave | | 1 |
| 54 | 3520C-154 | Spindle Index Pin | | 1 |
| 55 | 3520C-155 | Spring | | 1 |
| 56 | F006086 | C-Retaining Ring, Ext | S-9 | 1 |
| 57 | 3520C-157 | Cushion | | 1 |
| 58 | TS-1540071 | Hex Nut | #10-24 | 9 |
| 59 | JWL1440-141 | Strain Relief | M16 | 3 |
| 60 | SR-PG13.5 | Strain Relief | PG-13.5 | 1 |

| Index No. | Part No. | Description | Size | Qty |
|------------------|---------------------|---|--------------------------|------------|
| 61 | SR-6P3..... | Strain Relief | SR-6P3 | 1 |
| 62 | TS-081C062..... | Phillips Pan Head Machine Screw..... | #10-24x1"..... | 4 |
| 63 | JWL1642-169..... | Braking Resistor | | 1 |
| 64 | F000648..... | Phillips Pan Head Machine Screw..... | #10-24x1/4"..... | 1 |
| 65 | 3520C-165 | Inverter | | 1 |
| 66 | JWL1640EVS-163..... | Inverter Lower Box..... | | 1 |
| 67 | JWL1640EVS-161..... | Inverter Upper Cover | | 1 |
| 68 | TS-081C062..... | Phillips Pan Head Machine Screw..... | #10-24x1"..... | 2 |
| 69 | TS-081C052..... | Phillips Pan Head Machine Screw..... | #10-24x3/4"..... | 1 |
| 70 | F010749 | Flat Head Socket Screw | 3/8"-16x3/4" | 4 |
| 71 | 3520C-171 | Motor Mount Plate | | 1 |
| 72 | TS-0680041 | Flat Washer | 3/8" | 1 |
| 73 | TS-0209061 | Socket Head Cap Screw | 3/8"-16x1-1/4" | 1 |
| 74 | F014009 | Flat Key, Dbl Rd Hd | 3/16"x3/16"x2-1/2" | 1 |
| 75 | LM000302 | Motor Label..... | | 1 |
| 76 | 3520C-176 | Motor..... | 2HP | 1 |
| | 3520C-176JBC..... | Junction Box Cover..... | | 1 |
| | 3520C-176MF | Motor Fan | | 1 |
| | 3520C-176MFC..... | Motor Fan Cover..... | | 1 |
| 77 | TS-0680041 | Flat Washer | 3/8" | 1 |
| 78 | 3520C-178 | Lock Handle..... | 3/8"-16x1" | 1 |
| 79 | 6294744 | Face Plate Wrench | | 1 |
| 80 | 3520C-180 | Motor Cord..... | | 1 |
| 81 | 3520C-181 | Signal Cord (Inverter box to Encoder PCB box)..... | | 1 |
| 82 | 6294754 | Knockout Rod Assembly..... | | 1 |
| 84 | TS-0733031 | Lock Washer Ext Tooth | #10 | 1 |
| 85 | 3520C-185 | Sensor Collar | | 1 |
| 87 | TS-0267021 | Socket Set Screw | 1/4"-20x1/4" | 2 |
| 88 | 3520C-188 | Knob | | 1 |
| 89 | TS-2244102 | Socket Head Button Screw..... | M4-0.7x10 | 1 |
| 90 | TS-0253031 | Socket Head Button Screw..... | #10-24x1/2" | 19 |
| 91 | AP2-16 | Spring Pin | Ø6 x 25mm | 1 |
| 93 | F009669 | Socket Head Button Screw BO | #10-24x3/8" | 3 |
| 94 | 3520C-194 | Spindle Lock Label | | 1 |
| 95 | 3520C-195 | Fixed Plate..... | | 1 |
| 96 | 3520C-196 | Sensor Bracket | | 1 |
| 97 | 3520C-14110 | Signal Cable (Remote Box to Inverter) | | 1 |
| 98 | TS-2283102 | Pan Head Screw..... | M3-0.5x10 | 2 |
| 99 | 3520C-199 | Spindle Lock Guard | | 1 |
| 100 | 3520C-1100 | Sleeve..... | | 1 |
| 101 | 3520B-294 | Warning Label – Belt Adjustment | | 1 |
| 102 | 4224B-1124 | Warning Label – Faceplate | | 1 |
| 103 | 3520C-1103 | Main Switch (includes #104) | | 1 |
| 104 | TS-1512021 | Flat Head Screw | M4-0.7x12 | 4 |
| 105 | 3520C-1105 | Main Switch Box | | 1 |
| 106 | 3520C-1106 | Power Cable (Main switch box to Inverter, not shown)..... | | 1 |
| 107 | 3520C-1107 | Strain Relief, Motor (not shown) | 7N-2 | 1 |
| 108 | JWL1015-172 | Clamp | | 1 |


15.2.1 3520C Remote Control Box Assembly – Exploded View



15.2.2 3520C Remote Control Box Assembly – Parts List

| Index No. | Part No. | Description | Size | Qty |
|-----------|-------------|--|-----------|-----|
| 41 | 3520C-141 | Remote Control Box Assembly (includes # 41-1 thru 41-18) | | 1 |
| 41-1 | 4224B-148 | Switch Fwd /Rev | | 1 |
| 41-2 | 3520C-1412 | Digital Readout Display | | 1 |
| 41-3 | 6430047 | Knob | | 1 |
| 41-4 | 6295915 | Control Pot Assembly | | 1 |
| 41-5 | 3520C-1415 | Control Switch | | 1 |
| 41-6 | 3520C-1416 | Remote Control Box (includes #41-11) | | 1 |
| 41-7 | 3520C-1417 | Control Box Back Plate | | 1 |
| 41-8 | 4224B-1112 | Magnet | | 1 |
| 41-9 | SR-6P3 | Strain Relief | SR-6P3 | 1 |
| 41-10 | 3520C-14110 | Signal Cable (Remote switch box to Inverter) | | 1 |
| 41-11 | 3520C-14111 | Control Box Label | | 1 |
| 41-12 | 3520C-14112 | Wire (Control Pot to control switch, White) | | 2 |
| 41-13 | 3520C-14113 | Wire 2 (for control switch, Brown) | | 1 |
| 41-14 | 3520C-14114 | Wire 3 (control switch to Fwd /Rev Switch, yellow) | | 1 |
| 41-15 | 3520C-14115 | Signal Cable | | 1 |
| 41-16 | F010944 | Flat Head Socket Screw BO | M3-0.5x20 | 6 |
| 41-17 | 3520C-14117 | LED Light | | 1 |
| 41-18 | F010987 | Flat Head Socket Screw BO | M3-0.5x10 | 2 |


15.3.1 Spindle Centers Knockout Assembly – Exploded View



15.3.2 Spindle Centers Knockout Assembly – Parts List

| Index No. | Part No. | Description | Size | Qty |
|-----------|------------|---|--------------|-----|
| 82 | 6294754 | Knockout Rod Assembly (includes # 82-1 thru 82-7) | | 1 |
| 82-1 | TS-0270031 | Socket Set Screw | 5/16-18x3/8" | 1 |
| 82-2 | 3520B-287 | Slide Hammer | | 1 |
| 82-3 | 3520B-288 | Slide Handle | | 1 |
| 82-4 | 6295796 | Nylon Insert Socket Set Screw | 1/4-20x3/8" | 2 |
| 82-5 | 3520B-290 | Rod | | 1 |
| 82-6 | 3520B-291 | Retaining Collar | | 1 |
| 82-7 | 3520B-292 | Brass Tip | | 1 |


15.4.1 Bed, Banjo and Tailstock Assembly – Exploded View



15.4.2 Bed, Banjo and Tailstock Assembly – Parts List

| Index No. | Part No. | Description | Size | Qty |
|------------------|-----------------|--|------------------|------------|
| 1 | 3520B-140 | Powermatic Nameplate..... | | 1 |
| 2 | 3520C-202 | Backer Plate | | 1 |
| 3 | TS-0207071 | Socket Head Cap Screw | 1/4"-20x1-1/4" | 2 |
| 4 | TS-0680021 | Flat Washer | 1/4" | 2 |
| 5 | 3520C-205 | Bed | | 1 |
| 6 | 6295754 | Stop Bolt | | 2 |
| | 3520C-BA | Banjo Assembly (includes #7 thru 21) | | 1 |
| 7 | TS-0650081 | Hex Nylon Lock Nut | 3/4"-10 | 1 |
| 8 | 6294770 | Clamp | | 1 |
| 9 | 3058001 | Clamp Bolt | 3/4"-10 | 1 |
| 10 | 6710015 | Socket Head Cap Screw | #10-24x1/2" | 4 |
| 11 | F006048 | C-Retaining Ring, Ext | S-22 | 1 |
| 12 | 3520C-212 | End Cover..... | | 1 |
| 13 | 3520C-213 | Tool Rest Support Base | | 1 |
| 14 | JWL1440-206 | Locking Handle..... | 3/8" | 1 |
| 15 | 3520C-215 | Tool Support Rod | | 1 |
| 16 | TS-0271031 | Set Screw | 3/8"-16x3/8" | 2 |
| 17 | 3520C-127 | Lock Handle Assembly | | 1 |
| 18 | TS-0267021 | Set Screw | 1/4"-20x1/4" | 2 |
| 19 | JWL1440-207 | Tool Rest Lock Bushing Set | | 1 |
| 21 | TS-0570031 | Hex Nut..... | 3/8"-16 | 1 |
| 22 | 6295902 | Ball Bearing Live Center Assembly (includes #22-1 thru 22-4) | | 1 |
| 22-1 | 6295905 | Live Center Cap..... | | 1 |
| 22-2 | 6295904 | Live Center Tip | | 1 |
| 22-3 | 6295903 | Live Center Body | | 1 |
| 22-4 | 6295906 | Live Center Rod..... | | 1 |
| | 3520C-TA | Tailstock Assembly (includes #23 thru 49) | | 1 |
| 23 | 3520C-223 | Tailstock Quill | | 1 |
| 24 | 6295717 | Knob | M8 | 1 |
| 25 | 3520C-225 | Cover | | 1 |
| 26 | TS-1490021 | Hex Cap Screw..... | M8-1.25x16 | 1 |
| 27 | 3520C-227 | Lead Screw..... | | 1 |
| 28 | JWL1221VS-227 | Key..... | | 1 |
| 29 | JWL1640EVS-323 | Socket Head Button Screw..... | #10-32x5/8" | 1 |
| 30 | 6295910 | Lock Handle..... | 3/8" | 1 |
| 31 | 3520C-231 | Brass Bushing..... | | 1 |
| 32 | 3520C-232 | Tailstock..... | | 1 |
| 33 | 6760102 | Socket Set Screw | #10-32x1" | 1 |
| 34 | F006050 | C-Retaining Ring, Ext | S-25 | 2 |
| 35 | 3520C-127 | Lock Handle Assembly | | 1 |
| 36 | TS-0271031 | Socket Set Screw | 3/8"-16x3/8" | 2 |
| 38 | TS-0270011 | Socket Set Screw | 5/16"-18x1/4" | 2 |
| 39 | 3520B-125 | Tailstock Handwheel..... | | 1 |
| 40 | 3520B-126 | Swivel Handle | | 1 |
| 41 | 3520C-148 | Magnet..... | | 2 |
| 42 | F010987 | Flat Head Socket Screw BO..... | M3-0.5x10 | 2 |
| 43 | F009669 | Socket Head Button Screw BO | #10-24x3/8" | 3 |
| 44 | 3058001 | Clamp Bolt | | 1 |
| 45 | 3092095 | Clamp | | 1 |
| 46 | 6520009 | Nylon Lock Hex Nut | 5/8"-11 | 1 |
| 48 | 3520C-248 | Eccentric Rod | | 1 |
| 49 | 6095038 | Bushing..... | 7/8" x 1" x 7/8" | 1 |
| 50 | 3520B-251 | Comparator Rear Center | | 1 |
| 51 | 3520C-251 | Lock Handle..... | | 1 |
| 52 | 3520B-150 | Comparator Rear Bracket..... | | 1 |
| 53 | TS-0209061 | Socket Head Cap Screw | 3/8"-16x1-1/4" | 2 |
| 54 | TS-0720091 | Lock Washer..... | 3/8" | 2 |
| 55 | TS-0680041 | Flat Washer | 3/8" | 2 |
| 56 | 6294742 | Tool Support | 14" | 1 |
| 57 | LM000301 | I.D Label, 3520C (not shown) | | 1 |
| 58 | 3520C-258 | Black Stripe (not shown)..... | 3/4" x 51" | 2 |


15.5.1 Stand Assembly – Exploded View



15.5.2 Stand Assembly – Parts List

| Index No. | Part No. | Description | Size | Qty |
|-----------|------------|---------------------------|----------------|-----|
| 1 | 3520C-301 | Stand | | 2 |
| 2 | TS-0680042 | Flat Washer | 3/8" | 8 |
| 3 | TS-0720091 | Lock Washer | 3/8" | 10 |
| 4 | TS-0209061 | Socket Head Cap Screw | 3/8"-16x1-3/4" | 8 |
| 5 | 4224B-263 | Hex Nut | 1/2"-12 | 4 |
| 6 | 4224B-262 | Adjustable Leveler | 1/2"-12 | 4 |
| 7 | 3520C-307 | Riser Block | 4" | 2 |
| 8 | TS-0680061 | Flat Washer | 1/2" | 4 |
| 9 | TS-0720111 | Lock Washer | 1/2" | 4 |
| 10 | 3520C-310 | Hex Cap Screw | 1/2"-12 x 2" | 4 |
| 11 | 3520B-143 | Shelf | | 1 |
| 12 | TS-0209061 | Socket Head Cap Screw | 3/8-16 x1-1/4" | 2 |
| 13 | 3520C-313 | Black Stripe | 1/2" x 30" | 2 |
| 14 | 6294773 | Warning Label (not shown) | | 1 |
| | 1353003 | Riser Kit (#7 thru 10) | | |


15.6 Optional Accessories: #6294732, Outboard Turning Stand




| Index No. | Part No. | Description | Size | Qty. |
|-----------|----------|---|----------------|------|
| | 6294732 | Heavy Duty Outboard Turning Stand Assembly (items 1 thru 7) | | |
| 1 | 3042503 | Turning Stand Base | | 1 |
| 2 | 6295897 | Offset Tool Support Pin | 1.00" diameter | 1 |
| 3 | 6295898 | Offset Tool Support Casting | 1.00" hole | 1 |
| 4 | 2695026 | Screw Lock Assembly | | 3 |
| 5 | 3423055 | Turning Stand Leg | | 1 |
| 6 | 6861700 | Lock Washer | 5/8" | 2 |
| 7 | 6769002 | Socket Head Cap Screw | 5/8"-18 x 2" | 2 |

15.7 Optional Accessories: Bed Extension, Face Plate, Tool Supports, Guard

| Index No. | Part No. | Description | Size | Qty. |
|-----------|------------|--|---------------|------|
| | 1353002 | 20" Bed Extension Kit (includes #1 thru 6) | | |
| 1 | 3520B-310 | Extension Post | | 1 |
| 2 | 6294763 | Locking Handle | | 1 |
| 3 | 3520C-403 | 20" Bed Extension | | 1 |
| 4 | TS-0680041 | Flat Washer | 3/8" | 4 |
| 5 | TS-0720091 | Lock Washer | 3/8" | 4 |
| 6 | TS-0209081 | Socket Head Cap Screw | 3/8-16x1-3/4" | 4 |
| 7 | 6294742 | 14" Tool Support | | 1 |
| 8 | 6294739 | 6" Tool Support | | 1 |
| 9 | 6294740 | Bowl Turning Tool Support (RH) | | 1 |
| 10 | 6294751 | Bowl Turning Tool Support (LH) | | 1 |
| 11 | 6294728 | Guard Assembly | | 1 |
| 12 | 6143004 | Retaining Collar | | 2 |
| 13 | TS-0270011 | Socket Set Screw | 5/16-18x1/4" | 2 |
| 14 | 6294736 | Faceplate (includes set screws) | 1-1/4-8, Ø 3" | 1 |
| | 6295902 | Ball Bearing Live Center (not shown) | | 1 |




15.8 Optional Accessories: #6294721, Tailstock Swing Away



| Index No | Part No | Description | Size | Qty |
|----------|------------|-----------------------------|----------------|-----|
| 1 | | Front Plate | | 1 |
| 2 | PMSA-102 | Pivot Pin..... | | 1 |
| 3 | PMSA-103 | Twist Spring | | 1 |
| 4 | | Rear Plate | | 1 |
| 5 | PMSA-105 | Knob | | 1 |
| 6 | PMSA-106 | Spring | | 1 |
| 7 | PMSA-107 | Guide Pin | | 1 |
| 8 | TS-0209011 | Socket Head Cap Screw | 3/8"-16x1/2" | 1 |
| 9 | TS-0209061 | Socket Head Cap Screw | 3/8"-16x1-1/4" | 2 |
| 10 | TS-0720091 | Spring Washer | 3/8" | 2 |
| 11 | TS-0680041 | Flat Washer..... | 3/8" | 4 |
| 12 | PMSA-112 | C-Ring | S-11..... | 1 |
| 13 | TS-0271051 | Set Screw..... | 3/8"-16x1/2" | 2 |
| 14 | PMSA-114 | C-Ring..... | S-9..... | 1 |
| 15 | LM000011 | Warning Label (EN) | | 1 |
| | LM000065 | Warning Label (FR) | | 1 |
| 16 | LM000012 | ID Label..... | | 1 |
| 17 | TS-0561031 | Hex Nut..... | 3/8"-16 | 2 |

15.9.1 Optional Accessories: #6294901, Lamp Holder Set – exploded view



15.9.2 Optional Accessories: #6294901, Lamp Holder Set – parts list

| Index No | Part No | Description | Size | Qty |
|----------|------------|--|-----------------|-----|
| | 6294901 | Lamp Holder Set (<i>includes #1 thru 25</i>) | | 1 |
| 1 | 4224B-301 | Support Tube | | 1 |
| 2 | 4224B-302 | Lamp Holder | | 1 |
| 3 | 4224B-303 | Junction Box | | 1 |
| 4 | 4224B-304 | Current Overload Switch | 15A | 1 |
| 5 | 4224B-305 | Gasket | | 1 |
| 6 | 4224B-306 | Receptacle Cover Plate | | 1 |
| 7 | 4224B-307 | Strain Relief | PG11 | 1 |
| 8 | 4224B-308 | Power Cord | AWG14 | 1 |
| 9 | 4224B-309 | Socket with Cover | | 4 |
| 10 | TS-1533062 | Phillips Pan Head Machine Screw | M5 x 20 | 5 |
| 11 | 4224B-311 | Jumper (Black) | | 4 |
| 12 | 4224B-312 | Jumper (White) | | 3 |
| 13 | TS-0733041 | Star Washer | M5 | 2 |
| 14 | TS-1540031 | Hex Nut | M5 | 2 |
| 15 | 4224B-315 | Ground Jumper (Green) | | 4 |
| 16 | TS-0270011 | Set Screw | 5/16"-18 x 1/4" | 1 |
| 17 | 6143004 | Retaining Collar | | 1 |
| 18 | TS-1550031 | Flat washer | M5 | 4 |
| 19 | TS-1541011 | Nylon Hex Nut | M5 | 2 |
| 20 | TS-1481081 | Hex Bolt | M5 x 35 | 2 |
| 21 | 4224B-321 | Cord Restraint | | 3 |
| 22 | JML-59A | Lock Handle | | 2 |
| 23 | 4224B-323 | Holder Shaft | | 1 |
| 24 | TS-0253031 | Socket Head Button Screw | #10-24 x 1/2" | 5 |
| 25 | TS-069204 | Flat Washer | #10 | 2 |

15.9.3 Lamp Kit – Parts List

| Index No. | Part No. | Description | Size | Qty. |
|-----------|----------|---|------|------|
| | 6294901K | Lamp Kit (<i>includes #40-44</i>) | | 1 |
| 40 | 6294901 | Lamp Holder Set (<i>includes #1 thru 25</i>) | | 1 |
| 41 | 6294902 | Lamp (bulb not included) (<i>includes #42-44</i>) | 100W | 2 |
| 42 | * | Stud | M51 | 2 |
| 43 | * | Lock Washer, Internal tooth | 3/8" | 2 |
| 44 | * | Jam Nut | 3/8" | 2 |

NOTE: Powermatic lamps are supplied by Moffatt. For replacement parts indicated by an asterisk (*), contact Moffatt directly at 800-346-0761.