

## SERVICE PARTS LIST

**BULLETIN NO.** 54-07-2155

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS REVISED BULLETIN DATE June 2017 102 x 77 SPOT INFRARED IMAGER WIRING INSTRUCTION STARTING SERIAL NO. J<sub>02</sub>A CATALOG NO. 2257-20

**EXAMPLE:** 

00 0 Component Parts (Small #) Are Included When Ordering The Assembly (Large #).




FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.	FIG.	NOTE
1	31-21-2257	Battery Door Assembly	(1)	2	A clear
2	12-25-0214	Service Nameplate (Not Shown)	(1)		perforr

A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.