


## **SERVICE PARTS LIST**

BULLETIN NO. 54-04-7022

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS		REVISED BULLETIN	DATE
M28™ & V28® LITHIUM-ION BATTERY CHARGER		WIEDING INGTE	Nov. 2014
CATALOG NO. 48-59-2819	SERIAL NUMBER C49A & C49B	- WIRING INSTRUCTION	

 $\boxed{00 \boxed{0}} \frac{\text{EXAMPLE:}}{\text{Component Parts (Small \#) Are Included When Ordering The Assembly (Large \#).}}$ 



**FIG. PART NO.** 1 12-20-2911

**DESCRIPTION OF PART**Service Nameplate (Not Shown)

NO. REQ. (1)

FIG. NOTES

A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.