



BOSCH

Drill

GBM 6 RE | 3 601 D72 6B0

Table of Content

Spare parts list.....	2
Illustration - Type.....	3

Spare parts list

Item	Part Number	Description
1	2 609 100 741	Housing
2	2 609 120 279	Field 230V
4	2 607 200 623	Switch
5	1 604 460 262	Power supply cord CN 220V 2,65m 2 x 0,75mm H05 VV-F
6	2 600 707 062	Grommet Ø7x8,4 MM
9	2 609 131 664	Manufacturer's nameplate GBM 6 RE
13	2 609 110 745	Ball Bearing
14	2 609 110 491	Ball Bearing
16	2 609 120 356	Brush Plate
19	2 603 490 022	Screw 4x16
25	2 609 100 618	Reversing Switch
34	2 609 199 157	Bearing Bracket
46	2 609 110 746	Keyless Chuck
803	2 609 120 337	Armature set 230-240V
808	1 600 A00 YB9	Type Label
810	2 610 391 290	Carbon-Brush Set
841	2 609 120 405	Spindle Assembly

Illustration - Type - E

3 601 D72 6B0
 Stand) 09-11
 Issue) 19-03-20

Fig. /Abb. 1

