



BOSCH

Thread Cutter

GGW 10 E | 0 601 462 843

Table of Content

Spare parts list.....	2
Illustration - Type.....	4

Spare parts list

Item	Part Number	Description
1	2 605 104 309	Motor Housing BLUE
2	2 604 220 445	Field 220-230V
3	2 604 010 612	Armature 220-230V
3/60	2 606 610 049	Fan
4	2 607 200 184	Switch
5	3 604 460 184	Power supply cord H05 RN-F CN 2,65m 2 x 1,00mm
6	2 600 707 059	Grommet Ø6,9 MM
7	2 601 035 001	Cable Clip
9	3 601 110 341	Sticker SUNNY SIDE
13	1 900 905 018	Ball Bearing 7x22x7
14	2 600 905 021	groove ball bearing 9x24x7
16	2 604 337 003	Brush Holder
18	2 603 410 001	Socket head cap screw M3x6,5-4.8
20	3 601 110 342	Sticker SHADOW SIDE
25	3 606 135 003	Drilling Spindle 1/2"
26	3 600 210 065	O-Ring 13,0x2,0 MM
27	3 600 328 036	Bushing
28	3 605 190 131	Gear Housing
29	3 600 118 009	Spring retaining ring
30	3 600 101 043	Plain Washer
31	3 604 616 016	Compression Spring
32	3 600 101 044	Shim
33	3 606 316 071	Cylindrical Gear Z=42
34	1 903 230 011	Ball DIN 5401-6 G28
35	3 604 610 018	Compression Spring
36	3 606 316 020	Cylindrical Gear Z=42
37	3 603 300 007	Nut
38	3 600 118 010	Spring retaining ring
39	2 600 100 505	Shim 0,5 MM
41	2 601 328 033	Cover Disc
42	2 604 465 068	Suppression Filter
43	1 613 435 034	Lens Head Screw 3x10 ST
44	2 600 150 004	Shim
45	2 600 101 020	Shim 0,5 MM

Spare parts list

Item	Part Number	Description		
45	2 600 101 022	Shim	0,2 MM	
45	2 600 101 023	Shim	0,3 MM	
46	2 604 448 005	Cable	L=130 MM	WHITE
47	2 605 132 049	Housing Cover	BLUE	
48	2 604 448 097	Earth Conductor		
50	2 910 211 019	Tapping Screw	DIN 7971-ST3,9x16-F	
52	2 603 435 015	Cross Recessed-Head Screw	DIN 7981-ST3,5x9,5-F	
53	2 916 660 008	Spring retaining ring	DIN 472-24x1,2 MM	
54	2 600 500 002	Cupped Washer		
55	2 600 108 077	Felt Washer		
56	2 600 400 008	Receptacle		
57	3 606 328 000	Cylindrical Gear	Z=33/56	
60	1 603 435 036	Tapping Screw	4,8x78 MM, TORX T-20	
61	2 916 650 903	Spring retaining ring	DIN 471-12x1-FSTM	
62	3 603 124 000	Axle		
64	2 608 573 003	Chuck	M4-M12	
64/8	2 607 950 012	Chuck Wrench		
65	3 606 316 021	Cylindrical Gear	Z=28	
66	3 606 337 062	Spindle With Gear	Z=11	
67	2 603 435 012	Tapping Screw	79 MM	
68	2 600 100 613	Shim	0,50 MM	
69	9 001 140 359	Needle bearing		
90	2 910 211 022	Tapping Screw	DIN 7971-BZ3,9x25	
808	1 601 11A 3H3	Nameplate		
810	2 604 321 905	Carbon-Brush Set		
814	2 607 329 010	Service kit		
840	3 605 700 054	Intermediate Flange		

Illustration - Type - E

