



BOSCH

Cordless Drill Driver

GSR Prodrive | 3 601 JA2 081

Table of Content

Spare parts list.....	2
Illustration - Type.....	3

Spare parts list

Item	Part Number	Description
1	2 609 100 671	Housing
2	1 607 022 568	DC motor 3,6V
4	2 609 120 341	Electronics Module
5	2 609 100 687	Changeover Lever
6	2 609 100 686	Trigger
7	2 609 100 382	Light Conductor
9	2 609 131 790	Manufacturer's nameplate GSR PRODRIVE
12	2 609 110 838	Clip
45	2 609 199 188	Gear Box
61	2 609 110 535	Spring
62	2 609 170 058	Cover
91	1 607 A35 063	Battery Pack
101	2 609 110 361	Screw
653	2 607 225 529	Fast Charger CN 220/3,6-10,8V, 1h
808	2 609 132 012	Nameplate

Illustration - Type - E

3 601 JA2 000
 Stand } 08-05
 Issue } 10-06-15

Fig./Abb. 1

