




Model LXPH03 / LXPH03Z Parts List

A = Standard Equipment

O= Circuit Diagram

Item#	Part#	Description	Q'ty	Unit
	1	897154-0	LXPH03 NAME PLATE	1
	2	187432-9	HOUSING SET	1
	C10	263005-3	RUBBER PIN 6	2 PC.
	C20	252126-6	HEX. LOCKING NUT M4-7	2 PC.
	D10		INC. 28	
	3	266130-9	TAPPING SCREW BIND PT 3X16	7 PC.
	4	126100-9	SPEED CHANGE LEVER ASSEMBLY	1
	C10	233438-6	COMPRESSION SPRING 4	2 PC.
	5	419250-0	F/R CHANGE LEVER	1 PC.
	6	650683-2	SWITCH TG573FSB-4	1
	7	620139-9	LED CIRCUIT	1
	8	232220-0	LEAF SPRING	2 PC.
	10	424026-2	CUSHION	1 PC.
	11	251468-5	- FLAT HEAD SCREW M6X22	1 PC.
A	12	766015-4	KEYLESS DRILL CHUCK 13	1
	13	265995-6	TAPPING SCREW 4X18	4 PC.
	14	126099-8	GEAR ASSEMBLY	1
	15	638989-8	YOKE UNIT	1
	16	619301-1	ARMATURE	1
	17	638614-1	BRUSH HOLDER COMPLETE	1 PC.
	18	CB440	CARBON BRUSH CB-440 (195021-6)	1 SET
	19	263032-0	RUBBER PIN 4	2 PC.
	20	453394-6	REAR COVER	1
	21	266130-9	TAPPING SCREW BIND PT 3X16	2 PC.
	22	643859-8	TERMINAL	1
	23	424430-5	SEAL	1
	24	423422-1	SPONGE A	1
	25	911013-5	PAN HEAD SCREW M3X10	1 PC.
	26	423423-9	SPONGE B	1
	27	689176-2	HEAT SINK	1
	28	187432-9	HOUSING SET	1
	C10	263005-3	RUBBER PIN 6	2 PC.
	C20	252126-6	HEX. LOCKING NUT M4-7	2 PC.
	D10		INC. 2	
A01	126131-8	GRIP ASSEMBLY	1	
	C10	154935-8	GRIP 36 COMPLETE	1 PC.
	C20	266750-9	SQUARE BOLT M8X100	1
	C30	346566-9	GRIP SPRING 60	1
	C40	453584-1	GRIP BASE 60	1
	C50	265785-7	THUMB SCREW M5X10	1 PC.
	C60	931202-6	HEX. NUT M5	1 PC.
A02	251314-2	+ SCREW M4X12	2 PC.	
A03	346449-3	HOOK	1	
A04	452947-8	BIT HOLDER	1 PC.	
A05	784614-0	+ - BIT 2-45	2 PC.	
A06	122576-8	STOPPER POLE ASS'Y	1 PC.	
A07	***DC18RA	DC18RA FAST CHARGER	1 PC.	(LXPH03)
A08	BL1830	BATTERY BL1830 SET (195324-8)	2 SET	(LXPH03)
A09	450128-8	BATTERY COVER	1 PC.	(LXPH03)
A10	824754-3	PLASTIC TOOL CASE	1 PC.	(LXPH03)

C10	419216-0	HANDLE	1 PC.
C20	417724-5	LATCH	2 PC.
C30	419268-1	PLASTIC CASE LID	1 PC.
C40	419269-9	PLATE	5 PC.
C50	324667-3	SHAFT	1 PC.
E01	810300-8	CAUTION LABEL	1 PC.
D01	652045-0	+PAN HEAD SCREW M3.5X5	2 PC.