



## Model XRW01SR1/Z Parts List

A = Standard Equipment

O = Circuit Diagram

Item#	Part#	Description	Q'ty Unit
1	127297-7	HEAD ASSEMBLY	1 PC.
18	857Y45-7	XRW01 NAME PLATE	1
19	266429-2	TAPPING SCREW 3X16	7 PC.
20	183S01-8	HOUSING SET	1
	C10 263005-3	RUBBER PIN 6	2 PC.
	C20 819P58-2	CAUTION LABEL	1 PC.
	D10	INC. 36	
21	651391-8	SWITCH C3JW-6BM-PN	1 PC.
22	459422-5	LOCK LEVER	1 PC.
23	232353-1	COMPRESSION SPRING 4	1 PC.
24	459421-7	SWITCH LEVER	1 PC.
25	620E21-2	CONTROLLER	1
	D10	INC. 35	
26	643874-2	TERMINAL	1 PC.
27	857Y52-0	XRW01 SERIAL NO. LABEL	1
28	226897-1	INTERNAL GEAR 41	1 PC.
29	140K71-2	CARRIER COMPLETE	1 PC.
30	226898-9	SPUR GEAR 14	3 PC.
31	267235-8	FLAT WASHER 18	1 PC.
32	265A38-0	P.H.SCREW M3X6 WITH WR	2 PC.
33	310953-8	INTERNAL GEAR CASE	1 PC.
34	629A32-0	DC MOTOR	1
35	620B10-9	LED CIRCUIT	1 PC.
36	183S01-8	HOUSING SET	1
	C10 263005-3	RUBBER PIN 6	2 PC.
	C20 819P58-2	CAUTION LABEL	1 PC.
	D10	INC. 20	
A01	191A50-3	SOCKET ADAPTOR 9.5 SET	1 PC.
	C10 231952-6	RING SPRING 12	1 PC.
A02	191A51-1	SOCKET ADAPTOR 6.35 SET	1 PC.
	C10 231952-6	RING SPRING 12	1 PC.
A03	***DC18SD	DC18SD BATTERY CHARGER	1 PC. (XRW01SR1)
	D10	COMPO-PARTS	
A04	450128-8	BATTERY COVER	1 PC. (XRW01SR1)
A05	BL1820B	BATTERY BL1820B SET (197257-3)	1 PC. (XRW01SR1)
A06	832074-1	TOOL BAG	1 PC. (XRW01SR1)